

Important Safety warning



Playpen Lodge/Brent Oldwood with drawer

Article number 12500765

Serial numbers 698084 t/m 800000

The article and serial numbers can be found on the upper/downside off the base

Research has shown that there is a possibility to scratch off the foil from the spindles. This could harm your child.

It concerns the following products, Playpen Lodge/Brent oldwood with drawer from the series 698084 till 800000. The products are sold between June 2013 and June 2019.

If you have one off those products in use would kindly ask you to check if foils let loose. in case the foil let loose we ask you to stop using this product until the sides are replaced with new sides provided by Kidsmill or our dealers. In case the foil doesn't get loose we ask you to frequently check the sides. Also, we recommend requesting the new sides if the foil doesn't let loose .

By using the link below you will be able to request the new sides for your product. We kindly ask you the provide the serial number which is placed on slat base of the product. You could check if your product concerns this problem by looking at the grooves on the inside of the sides. if there are 2 grooves on the spindle your product does have this safety problem. If there is only one groove your product doesn't have this problem and there is no need for new sides.

You could request the sides [here](#).

If you are not sure or your product concerns this product or if you have other questions, you can contact us by email on the following address: Service@timgro.com

Timgro B.V.

Hogeveldseweg 2

4041 CP Kesteren

